
GOVDOC BRA 1146






gov. 17 266

REPORT OF LAND USE AND BUILDING CONDITION SURVEYS
FOR THE CENTRAL BUSINESS DISTRICT URBAN RENEWAL AREA

Prepared by: Boston Redevelopment Authority Staff



CBD B65 R. RepL c.1 1963



### I. Introduction

This report was prepared by staff members of the Authority under the supervision of the Development Administrator.

It includes a listing of the land use and building condition surveys that were made by staff members and consultants to the Authority, an outline of survey procedures, a statement of the standards employed, and a summary of the results of the several surveys.

#### II. Background

In 1961 the Authority undertook exterior surveys of land use, building occupancy and building conditions throughout a large part of the City of Boston. The field survey information, statistically integrated with 1961 City of Boston Assessing Department data, formed the research material essential for general planning and for the preparation of the ten General Neighborhood Renewal Plans, including the Downtown area in which the Central Business District is located.

Because of the recognition of the complexity of structures and occupancy and the value and importance of real estate and economic functions within the Downtown area, buildings within this area were surveyed in greater detail than elsewhere in the City and interior inspections were conducted in all buildings where entry was permitted.



The information obtained provided planners and administrators with a comprehensive understanding of the Downtown area as a whole and enabled basic initial decisions to be made—for example, to set project boundaries within the area and to outline proposed priorities and to define scope of renewal activity.

When project planning was undertaken for the Central Business District Project in 1963, more detailed, accurate and timely information was required. Therefore, two major statistical inventories were undertaken—a land use survey and a survey of building conditions. Descriptions of these studies follow.

## III. Land Use Survey

# A. <u>Survey Procedures</u>

In the period 1963-1964, the Boston Redevelopment Authority staff undertook a comprehensive land use survey of all the properties within the Central Business District Project Area.

The survey was carried out according to procedures established by the professional planning staff of the Authority. At that time the economic consultant for the Central Business District outlined specific data requirements to be fulfilled by this survey and advised the Authority on data collection and analysis procedures.

A standard field survey form was developed for recording detailed data on each establishment on a floor-to-floor basis as



well as specific information for each building as a whole throughout the Project Area. Also the form provides for recording all quantitative findings developed by the office research staff.

The attached sample field sheet indicates the range of data items surveyed and collected and includes the following: the number of enterprises or establishments, name and description of each enterprise or establishment, Standard Industrial Classification category, space-using "activities" within each enterprise or establishment (i.e. office, storage, production space, etc.), amount of floor area for each enterprise or establishment and "activity" unit therein, and the amount of vacant space, if any, on each floor.

The observation and collection of field data was limited to "net" floor space. Corridor, elevator shaft, or basement and storage space attributable to normal building operation and maintenance was not subject to inspection and data recording in the field.

For the building as a whole, observed renovation activity was described and located. Also the existence of any passageway, corridor, or open floor access into adjoining buildings was noted and located.

All buildings were entered and examined by the staff of the



Authority with the following exceptions:

- 5 historical buildings;
- 2) 11 vacant (locked and boarded up) buildings;
- 3) City Mart building;
- 4) 3 buildings to which access was denied;
- 5) Approximately 20 Chinese residential buildings;
- 6) 10 city parking garages.

Information on this group of buildings was obtained, as needed, from business directories and other appropriate sources.

Surveyors entered and examined each building in its entirety and recorded information on a floor-to-floor basis. Completed field sheets were periodically rechecked in the field by the supervisory staff to insure that all items were being recorded accurately and in accordance with survey procedures. All survey forms were then reviewed and checked in the office for completeness and internal consistency.

The data was processed and analyzed by the Authority staff to obtain summaries for each building, for each block, and for the entire Project Area. Attached are the summaries for the total Project Area.

The form "Activity by Floor" summarizes all buildings in terms of ten basic space-using activities, and the form "Enterprise by Floor" summarizes building occupancy in terms of detailed economic categories.



In addition, the Project Area was divided into functional subareas. The map illustrating these subareas is included with this report. The extent of each kind of occupancy found in the several subareas was compiled both in terms of the original "activity" and "enterprise" categories and by a system of generalized cross-tabulated categories found useful for planning analysis.

Table I attached to this report summarizes building space use by five generalized occupancy categories.

# B. <u>Utilization of Survey Results</u>

Full, detailed, and accurate information was obtained from the Land Use Survey for the use of the Authority and its consultants.

Summary findings of building use by economic categories

(Standard Industrial Classification) provided the economic consultant the necessary research base to develop conclusions on the economic role of the Central Business District in relation to the city as a whole and to the metropolitan region.

The statistical summaries have been used to measure the economic activity in various buildings and groups of buildings within the Project Area and to measure current economic activity against future potential. The summaries have also been used to estimate the number of persons employed, the type of employment in various areas, and the resulting demand for public and private facilities by such persons.



Particularly important has been the knowledge gained on both vacancy rates and the location of large amounts of vacant space as an indication of building space marketability and economic return.

Also, the descriptive data on the location, by floor, of various activities or the location of passageways between adjoining buildings was of considerable aid to staff architects in developing building and site design studies.

Finally, of primary and continuing importance were the initial field survey sheets containing complete information on the occupancy of each building. Included were the names and locations of businesses and the amount and type of space used, along with floor and building footage totals. From this basic resource material information about the location of various types of businesses—for example, all the eating and drinking establishments in the Project Area, or all the government offices occupying rented space—was readily available for special studies as needed.

# IV. Building Conditions

### A. Survey Procedures

A survey of the physical condition of buildings throughout the Project Area was conducted during 1964 and 1965 by the Authority staff and its consultants. The purpose of the survey was to obtain up-to-date information on the actual structural characteristics of the buildings, so as to measure the extent and nature of



building deficiencies within the Project Area. The survey was intended to provide necessary factual data to enable the Authority to consider the eligibility of the Project Area under State and Federal law and to use the results of the survey in deciding on what planning measures should be adopted as part of the urban renewal plan.

Because of the large size, complexity, and variety of types of buildings, the Authority retained the professional engineering firm of Charles T. Main, Inc., of Boston, to conduct building condition surveys of approximately one-half of the buildings within the area. The choice of the buildings to be surveyed by the consultant was based on the surveys undertaken three years previously. Charles T. Main., Inc. carried out its part of the work with the use of professional engineers under the supervision of an officer of the firm.

Members of the Boston Redevelopment Authority staff accompanied the consultant's engineers throughout this survey. Under the supervision of the Project Engineer, these men then carried out interior inspections for half of the remaining buildings within the Project Area.

The attached map shows the buildings which were surveyed by Charles T. Main, Inc., the buildings surveyed by the Authority staff,



and the buildings to which access was denied. In cases where access was denied, an exterior survey was made.

Survey information was recorded on the Building Examination Schedule developed by the Authority. This form was based on forms used by the Authority for non-residential properties in other project areas. Minor additions were made on the advice of Charles T. Main, Inc. in order to meet the unique conditions found in the Downtown area. A copy of this form is attached. The survey form provided for the recording of all pertinent information concerning the type and condition of walls, floors, ceilings, roofs, exits, major mechanical equipment, fire safety fixtures, utilities and other fixtures within all structures.

All buildings for which survey forms were filled out in the 1964-1965 Charles T. Main, Inc. and BRA survey were scored by averaging the scores noted on the forms.

After such numerical scoring took place, the results were checked by the Chief Planner and Chief Architect for the Project to insure that the results obtained from the numerical scoring were consistent with observed conditions and reflected an accurate summary of the building conditions found in the Project Area.

Also, the scoring results were checked by the Chief Planner and Chief Architect to insure that a consistent level of evaluation was employed throughout the survey area by the several persons who inspected the buildings.



It should be noted that the following historic buildings were not examined and, for the purpose of tabulating survey results, were considered to be standard:

The Old State House
The Old South Meeting House
City Hall
St. Paul's Cathedral
The Old Corner Bookstore

# B. Survey Standards

The Authority staff established standards for evaluating all buildings within the Project Area. These standards were developed pursuant to federal law and are consistent with standards employed by the Authority in other projects previously undertaken.

All buildings were classified as standard, deficient, or structurally substandard requiring clearance.

A structurally substandard building is one containing two or more "structural defects", or one such "structural defect", plus defects in more than 25% of those "minor items" that were examined and scored.

A deficient building is one containing one "structural defect", or defects in more than 25% of those "minor items" that were examined and scored.

All other buildings are standard.

A defect was found to exist if the item examined was more than 25% deficient. If it was possible to measure the width,



length, area, or surface of the item examined, then the 25% was taken of such width, length, area or surface; otherwise, the 25% was a measure of the degree or intensity of the defect.

If the same item was examined on several floors, the average of the per cents of deficiency given to the condition of such items on each of the floors was used.

"Structural defects" consist of the following:

## 1. Interior Walls

- (a) Cracks in base material;
- (b) Base material loose, missing or broken;
- (c) Evidence of leaks.

# 2. Floors

(a) Sagging or pitched.

#### 3. Roof

- (a) Roof material loose, missing or deteriorated;
- (b) Roof sagging or out of line.

### 4. Foundations and Basement

- (a) Exterior surface loose, broken or deteriorated;
- (c) Basement foundation walls deteriorated;
- (d) Columns or piers loose, missing, or deteriorated;
- (e) Framing split or deteriorated.

# 5. Exterior Walls

- (a) Masonry and joints loose, missing or deteriorated;
- (b) Other siding loose, missing or deteriorated;
- (c) Walls out of plumb or line.



Other elements of a building as listed on the Building Examination Schedule were considered to be "minor items".

In addition, utilities were examined for plumbing, heating, electrical and fire code violations.

# C. Survey Results

Pursuant to the standards described above, 234 (35.3 percent) buildings were graded "standard", 235 (35.4 percent) were graded "deficient", and 194 (29.3 percent) were graded "substandard".

Building condition was based on a maximum of 135 separate ratings in 29 categories (see attached survey form).

Of the 474 buildings for which interior surveys were made, the following had one or more defects in the structural items indicated:

- Interior Walls (cracks in base material; base material loose, missing, or broken; evidence of leaks)
  65 (13.7%)
- 2. Floors (sagging or pitched) 48 (10.1%)
- 3. Roof (sagging or out of line; material loose, missing, or deteriorated) 93 (19.6%)
- 4. Foundations and Basement (inside or outside surface loose, broken, or deteriorated; foundations deteriorated, sinking, or out of line; basement columns or piers loose, missing, or deteriorated; basement framing split or deteriorated)


  81 (17.1%)
- 5. Exterior Walls (masonry and joints or other siding material loose, missing, or deteriorated; walls out of plumb or line) 87 (18.4%)



Other results of the building condition survey are as follows:

128	(27.0%)	had defective, inadequate, or deteriorated <u>plumbing</u> .
75	(15.8%)	buildings had <u>elevators</u> that were obsolete or defective.
175	(36.9%)	buildings had exposed <u>wiring</u> or other defects in the electrical system.
100	(21.1%)	buildings had inadequate or unsafe boiler rooms or heating systems.
26	(5.4%)	buildings had inadequate <u>fire</u> protection.

The above findings, relative to the above group of 474 buildings, were representative of all buildings within the Project Area.



	ON REDEVELOPMENT AUTH Building Space Use Su			Assess Assess				BRA Bldg Pg. / Exam. by Date Ca	of /						
	ess			Bild. Neme Glonial Bldg.  Bild. Address 127 Line-In St.											
Fl.	Establishment	#E	Enterprise Description	SIC	Act.	%F1.	Fl.	Bldg. Sq Total	of,						
	IN & In stan of Co.	1	Misc. Bus. Servic	1. 1	_, ,	10		1,200							
	Kilm To ten		Tax Consultante	29 =	.4	10		1,200							
	In B. Dr. 11	1	Dentist	212	1-1	10		1,200							
	Ep : 121 + 510 -	/	Komen's Clothes	562	.R	30		3,610							
			(Storges)		D	20		2,400							
	John's 51195	1	Shoe Store	560	L	20		2,400							
2	When a distribution of the state of the stat						2	12,000							
	Episialty Sicp		Vicmon's Clothe	5.2	B	50		6,000							
	John's hors		Shoe Store	F	/_	20		2,400							
	Sint ich Bar	1	Restaucent	5-		10		1,200							
	1/11/ 13 11		Drug Store	513		10		1,200							
	* , 211 + 1 2 CT		Card Shep	599		5		100							
	Vive			00	C	5			600	5					
1							/	12.000							
	Whice Dittibute -	1	Jamilara (ratail	517	1-2	30		2,040							
			(repair shop)		("	10		280							
	"Coft o An Shop.	1	Restaurant	.581	B	30		2,640							
	7. 10	1	Barber Shep	724		10		880							
	11 + Lan	1	Women's Hats	563		20		1,760							
R						·	B	8,800							
		12	TOTAL					32,800	600	1.8					
Renov	vation Activity: 7.03	s <i>†</i>	floor*	Setbac			B/1 2	Parcel A:	rea <u>/2,/4</u> 9 10	<u>'/</u>					
Addit	Access: (to Bldg.	nt	space being	Hote: E.	usem. 1	Green	ŞT.	functions First floor	as firs	+					
Lune	is and propared for	re	TWIT SUICS	-to LE	SCCOII	4,016.		Page /							



BOSTON REDEVELOPMENT AUTHORITY Downtown GNRP, Land Use Survey

Activity by Floor Project: CBD Assess. Blk Sub-Area Total BRA Bldg.

Project Total 2

14		13	검	7	10	01	ω	<u></u>	9	2	4	m	CU	Н	þτ	4	83	H	
TOCALA	178700	191,400	239,500	478100	63,100	773 400	1044 600	1207.190	1773 290	3,500,115	2963015	3164 970	333620	36567200	V88 1646	STA STOOK	232 880	1353,165,041.69,195	
Pkg.	331.	630	12,6cc	12,600	009 701	3.55	2.30	1000	11115 37	11/1/2 24	172,800	000,000	186 900	188 805	777		2) 6:	1353,105	Н
	85.53	62,300	62,30	83.90	108,800	111,36	114 800	13.50g	124,988	12:20	112,900	13.8%	US 905	25,695	7.9%			1,513,370	H
Consp			1	3.150		13 300	1000	5.20	35160	3	13400	1000	7340	475,68	2/2 435	77700	25:00	776 843	Ü
Rec.			18/20	3,500	3,200	16,320	1325.	28,110	34,455	12677	118/22	185,960	283715	167218	5/0/0		13.00	182.281	Fre
Goods Prod.	3,165	21,300	5.400	8 520	19,995	41.,x92	64,036	1. 2. C.	198.590	222/2/2	328,035	335 310	380,936	75, 250	77700 3/11	772	Open	1918 859	E
Storage		· Community of Community	0HC 74	11,400	10,250	0201/20	2000	53,600	287140	5.	3/67/3/12	485 195	404,059	253.051	10.11 Mes		72630	3375 570	D
doug			2,570	720	11,1.50	10,735	12720	13,485	43,760	57.50	54 405	72,105	-	75,950	25,020	77.76	1,440	1455.370	Ü
prole	-				1,650	33 (75	250	75.6:3	156,695	5.25.15	405.835	4/3,015	522115	1194, 805	200 000		77.830	3513100	ĽΩ
OIIIce	1.9,035	101,500	010 901	329,555	1/27 776/7	4.41.		5.7.7.	674 013	manufacture from the formation of the second	22/1977	942,335	92	0000	101 27/		1.8 555	188 831	⋖
Vacant			15,630	1000	3,475	11/2.2		Anthropological Contraction	1000	1 - 5.0	3.9.45	35575	3340	11.07				1994	8
	F1007	13	27	11	10	01	$\infty$	<u></u>	0	5	7	m	N	Н	р	1	93	H	



BOSTON Downto	Ac	tiv.	ity	by F	<u>'loor</u>	Su	b-Ar	ea 7	To	BR	A Blds	lk						
	74	13	27	11	750 OI	800	\$ \$ \$	74	200	7.	10 4	8 17	91 &	3 15	Д	SB	E	
Row					3,300	5,000	8,400	15,500	15,500	15,700	16,000	12,000	48,150	58 950				
I Vehic. Pkg.			1				1							7				Н
H Resid.		1	1		7	1	1		1									Н
Food			1		7		1	And the second s	1								Section Control	Ů
Assemb Rec.		1	1		1	1	1	1	1	1	1	1	3860	23 810		1		ſĿι
Goods Prod.																		ঘ
Storage		and the second								The state of the s			5,750	5,750				a
Shop																	6	Ö
Store																		æ
Office					3,360	5,000	1975 C	15	12 260		16,000	12:21	32,500	37862				A
Vacant							-									,		8
	Floor 14	13	12	Ħ	10 24	× ×	95	0-	9	77	\$ 1 to	317	2 /6	727	р	55	E-I	



								HORITY Survey	•	Enter Floor		e by		Proje Sub-A				zsess RA Bl		k	P-Visiting.
					-, -							CI	30	Tota				Pg			7
		01-14	15-17	19-39	64-04	20	52-59	* 52.	* \$ 12.00 \$ 12.00	* * * * * * * * * * * * * * * * * * * *		29-09	70-89	70	75-76	1	ŧ	88	31-94	Total	
נטיידים	1000/	1,995	53,210	2396 815	155,319	2,340,130	6.2.6,431	3573,095	51,846	227,830 800,034	(4/679,852)	2898,746	6,500,127	1,441,322	1446,005	652,190	671,075	177,605	1,303,540	34668,695	
0.1	OT VY	120,472	2,200	68,955	21,700	15,876	29,455	220	407		ſ£,	F.	335,530	245	15,08 13,08	3779	030		59,440	633.10	10
C		1,230	3470	72,095	01928	3250	85,710					057.1/H		300	45,23	12/9/20	45,055	1	31,700	723400	6
X	11 -	12000	3,160	105,035	46,080	20,270	124,510	375,000	070.07	1 55 160		166,295	403540	10,440	21,825	18,000 17	数 (2000) (2000) (2000)	1	76,37	104/6 100	80
7	46, 105		180	115,430	49.370	66.880	174 620	154,200	10.70	4 5		150,840	467.905	2012 2115	28,975 104,030	155 E	59,355	1	1055331	0618001	7
9			7330	3025205	49.235	133,390	348,395	387,000		1001X		5/976/	478 200	112,000 23,060	20,000	57.75	(20g)	2,380	99.120	1778 270	9
ľ	3337/5	1332 1332	40140	352 945	90,290	220,520	521,950	25,590	109.515	200 m		235, Z50	665, 950	124,150	15 825 154 920	1888 S	50,876	3,900	120,9110	2,502,	5
17	277 126	A STATE OF THE STA	6,870	383,770	.55,510	333,400	089 977.9	412032	1 73	388		35/305	793,900	135/70	A SERVER	05/480	12 280	28,32	135,633	2,464,	t
cr	3.5.77		4,900	382,560	68.200	356,225	073870	14, 100	182,33	37 92 92 92 92 92 92 92 92 92 92 92 92 92	Andrews Veneralifica	329 455	868400	124,770	35050 3500 3500 3500 3500 3500 3500 3500 3500 3500 3500 3500 3500 3500 3500 3500 350	48,370	98,000	63,150	120,905	3164	m
2	32,43h		07.20	268010	01+271	376,505	38.856 175	438,588	\$ 500 E		35%	067 278 8	33/15/245	52	2/3/2	2/2/3	3233	56,650	121,965	M33337	2
7	150,847		010000	077,101	122529	751,095	1,64,691.38.33.1155	57.57.5	3,012	333		346781 8347,790	653,997.9345,945		266970	16. 200 S.	16.230 18.230	19,225	83,025	15%	-
北 Base	143	1-19	S (5) (5) (5) (5) (5) (5) (5) (5) (5) (5)	36	11/4.873	1875	760	1 2 2 7 2 5 2 5 5 5 5 5 5 5 5 5 5 5 5 5 5	10 Colored	30 0 mg		10 525. 17 J ZZO	16 319.	50,000	2000 2000 2000 2000 2000 2000 2000 200	197		3/16.	S! S3 Z81 Z	472.7.7	36 % E. W.
	O Vacant		Const.	9 Manuf.	40-49 Util.	50 Whsale	9 Retail	2 Hard. 3 G.Mrch.		Furn. S. M.tTr.	F.Sales	F.I.R.	Serv.		Fepair Rec.		Misc.	Resid.	Gov.	Total	
	J	01-14	T=C7	19-39	4-04	7	52-59	* 528	に ※ ※	* *	#.6.A.F	29-09	70-89	70 72 72	75-76	82-86	68	88	91-94	Column	



								THORITY Survey	A management	apad	se b	Σ΄.		Sub-	ject_ Area	10	/ B	RA B	s. Bl ldg.	
												3	)	Tot	0/	.2		-8.		
	0	01-14	5	19-39	64-04	50	52-59	0 m	* * * * * * * * * * * * * * * * * * * *	53		00-04	70-89	70	73	78-79	82-86	88	91-94	Total
TOURT		(	6	,	6	Ć							,	6						
77	^		,	,	-					1 5	and the	777		,					7,890	15,020
Y	î	,			)							7						1	7.930	65.722
D			1								8	135							7,80	8
		-,-		,							. 11. 5	7550							7,820	17-30
	1				1						0 1/2	727	5,720	5,750				1	23.00	48,150
		-						.			10 /10	7.000	6.950	5,750	1 2000			1	33.75	58,850
+	-	-	-	18,325	5,30	11,605				to objections produced to the state of the s	30.07.63	5/10	19.5%	18 300 18 300	3,30	100	53/46		33,000	178700
	1		,	15/00	5.20	7.83					40 646		87/10	63,300	129		13000		3303	1915/20
1	CEV'07	-,-		15,650	5,320	1.880	2015			1	54/ 200		1118115	12. 30 B	6,528	10,875	1840		35,580	23%;300
	20,80	7	75%	38.30	12,970	25,150	17.070	10,520			1.20.79.	777 CVA	138,465	3.26	1987	15 SS	3775		57.88	4300
		-									4			1.			11		,	并E Base
		15-17 Const		19-39 Manuf.	40-49 Util.	50 Whsale	52-59 Retail	\$2 Hard. *53 G.Mrch. 54 Food	\$5 Auto *56 Apprl. *57 Furn. 58 Eat-Dr.		60-67 F.I.R.	1	70-89 Serv.	70 Hotel		78-79 Rec. 81 Legal	82-80 Inst. 89 Misc.	88 Resid.	91-94 Gov.	Column Total



	BOSTON REDOWNTOWN						Enterpr Floor				Proje Sub-A	rea			BR	A B	Bludg.		
	0 01-14 15-17	19-39	64-04	50	52-59	* * * * * * * * * * * * * * * * * * *	(BD)		1 29-09	2/ 68-01	70 77	73	78-79	32-86	68	88	46-16	Total	
Total			3													-	discontinuo di contra di c		
10								*G.A.F.		-	1.				1			,	10
6		Speciment of Processing	Bardingham Empresa	1	and make	4 1 1			1	1							-		6
00			Company Common			1 1 1 1							1 1	1			**************************************		8
7		8	Contraction of Processing	-						-				Special control of the second			Samuel Comments	6	11
9			1	1					1	-	1				1	1			- 9-
5			Processing Community							Company of the second of the s					1			•	5
24		3376	6	1						Springing parties	1				1		Backgrown C. charge	3,360	(C)
73		3560	Contraction Contraction												1		Basedider size of flue.	2,62	
2		70.31	-	-	-		(		7,360						1		the same	3,400	Į.
21		~			1		6		7722	1	1				1	1	2500	125,07	
E Base										1					1				-
	O Verent The config.	o 19 Print.	0-49 Util.	50 Whsale	2 Pretail	52 Hard. %53 G.Mrch. 54 Cord. 55to	Appril.	Sales	0-57 F.I.R.	0-39 Serv.	70 Hotel	73 Bus. 75-76 Repair	8-79 Rec.	2-35 Inste.		38 Pasid.	1-54 Gove	fr 5 1.0	






TABLE I

## BUILDING SPACE USE

## GEMERALIZED OCCUPANCY CATEGORIES

Areas	Total Sq. Ft.	Retail Sales	Service Retail	Office	Other	Vacant
Upper Washington	2,573,735	500,655	541,945	069'766	296,760	239,685
Ladder Blocks	2,720,840	1,315,550	306,320	548,535	320,375	230,060
Washington Summer	3,111,200	2,747,635	208,260	43,485	40,220	71,600
Church Green	2,695,410	361,665	506,360	632,735	831,175	363,475
Financial District	3,983,200	118,330	100,980	3,137,670	578,785	47,435
Garment Chinatown	1,823,610	80,480	115,440	551,675	815,615	260,400
Hinge Area	2,743,330	178,105	747,250	399,045	1,104,225	314,705
Park Square	2,694,530	215,062	1,530,786	309,251	496,319	143,112
Leather District	2,213,540	7,520	245,155	1,144,760	509,380	306,725
Total	24,559,395	5,525,002	4,302,496	7,761,846	4,992,854	1,977,197





3 9999 06315 114 4



## Report Binder Stock No./Color

80571 Black 80572 Lt. Blue 80573 Dk. Blue 80578 Rust 80579 Exec. Red

TAADE IN THE USA

